

**Detección
de roturas**

DEMO REPORT





Detección de roturas DEMO REPORT

Date: May 25, 2022.

Location: Demo Farm, 12345, 12345

Cage: XY123ZZ

ALERT - HOLES DETECTED!



HOLE INFO

Depth: -18.8 m

Heading: 217°

Estimated hole area: 320 cm²



KARMENstudio

advanced aquaculture video analysis

